


PARTIAL LOAD LOSS

What Happened – As Driver was transiting from the trailer park to the Live Load area, to get assistance with strapping his load, as he has turned out of the Trailer Park 2 road to enter Trailer Park 1 the near side gun-barrel coil has fallen/ rolled off the trailer to the ground and been severely damaged.



Findings –

The Driver did not Book In on arrival, so no one was aware he was on the trailer park to assist him.

Driver claimed he had checked the load and a piece of wood was missing? No evidence taken to support this.

Driver had not applied any straps on the load at all for the transit to Live Load area, which would have prevented the coil moving.

Driver did not close the curtain before transiting which may have stopped the coil falling from the trailer.

Drivers must Check:-

- ✓ Drivers **MUST Book IN** before going to the Trailer Parks. (As per attached).
- ✓ Is the load configuration correct? If not take a photo and **REPORT IT! DO NOT MOVE UNTIL CORRECTED!**
- ✓ **ALL** Loads **MUST BE Strapped in the Trailer Park** as per instructions attached.
- ✓ **NEVER** Transit anywhere without applying straps. To assist placing of shunt straps **BOTH curtains MUST BE prepared** for the loading (As per attached).
- ✓ **Always** close trailer curtains before transiting between sites.



Report any issues directly with the Dispatch Office on site.