

TATA STEEL STRIP PRODUCTS – LLANWERN WORKS, NEWPORT.

Loading:

Monday - Friday 08:30 to 17:00 (on site by 16:00) Saturday-Sunday Check

PPE Requirements:











Additional Information:





Reporting/Arrival:



On arrival stop at security

Loading bay




Drive to trailer park Do not prep trailer until instructed to by P&O Checker



Report to drivers reception with full PPE and loading reference Wait for instructions.

Loading/Securing:

Stand in green area during loading











No loose or damaged well boards

Straps LC 2000 daN



Steel Coil Loads:

NO CUTS






No Climbing – Use trailer steps or mobile steps




Clean and tidy trailer bed

LOADS MUST BE SECURED IN THE LOADING BAY - PLEASE HAVE STRAPS READY BEFORE ENTERING THE BAY



continental Europe





TATA STEEL STRIP PRODUCTS – LLANWERN WORKS, NEWPORT.

Loading:

Monday – Friday to 17:00 (on site by 16:00) Saturday-Sunday Check

PPE Requirements:













Additional Information:









Reporting/Arrival:



On arrival stop at security

Loading bay




Drive to trailer park Do not prep trailer until instructed to by P&O Checker



Report to drivers reception with full PPE and loading reference Wait for instructions.

Loading/Securing:

Stand in green area during loading











Straps LC 2000 daN





NOT WORN

No loose or damaged well boards





Clean and tidy trailer bed Steel Sheet Pack (AFL) Loads:

LOADS MUST BE SECURED IN THE LOADING BAY - PLEASE HAVE STRAPS READY BEFORE ENTERING THE BAY



14 Straps & Ratchets required



Edge protection is required

4. Overview of restraint system - export loads

