

## British Steel, Scunthorpe RODMILL Collection Plan

Loading:

PPE Requirements:


## **Additional Information:**











Monday - Friday 0600-2200



ON ARRIVAL STOP AT M&G VIA
SECURITY GATE A



AFTER INDUCTION GATE D













Loading/ Securing
Stay in Green Area during Loading





DOORS MUST BE KEPT CLOSED WHEN DRIVING ON SITE





Straps MIN LC 2000 daN



MIN X 14 MAX X 16



NO CUTS






LOADS MUST BE SECURED IN THE LOADING BAY OR THE TRAILER PARK – PLEASE HAVE STRAPS READY BEFORE ENTERING THE BAY

**SECURING INFORMATION ON REVERSE** 

## LRG 0019 12 Coil Load XL Headboard

## ALL EXPORT LOADS MUST BE LOADED AS FOR A 2 AXLE TRACTOR UNIT TO AVOID AXLE WEIGHT ISSUES ON THE CONTINENT





Export Load - Ratchet positions and direction of pull

