
## alert bulletin



AB 007 2024

## DRIVER INJURY DUE TO NOT ADHERING TO CORRECT PROCEDURE

What's happened: Driver has loaded and is closing up his trailer roof using a roof pole from the ground. The driver was walking backwards and according to witness, almost at a jog. Part way along the roof jams causing the driver to fall backwards and hit his head on a steel bar adjacent to the trailer. Driver sustained a cut to the head.





## Findings :

Driver was wearing full PPE including helmet but not chin strap. No defects reported on the trailer prior Driver was walking backwards and using excessive force. Procedure is to walk forwards or sideways on slowly so if roof does stop then there is less likelihood of fall or injury

## **Recommendations:**

- ✓ Always adhere to the safe working procedure for any task
- ✓ Familiarise yourself regularly with the correct standards
- ✓ If roofs are stiff then always seek help



Always report any defects so to avoid the next person having issues or worse still

injuring themselves.

